

Canusa SuperCase™ CSC-X


Two-piece, heat-shrinkable casing system for pre-foamed, pre-insulated pipe joints

Product Description



The fully shrinkable Canusa SuperCase™ - CSC-X is a crosslinked, heat shrinkable casing system for pre-foamed or foam half-shell filled joints on pre-insulated pipes. The CSC-X uses Shrink Film - WC-20R and SuperCase Adhesive - SA to seal the joints.

General Information




These installation instructions are intended as a guide for standard products. Consult your Canusa representative for specific projects or unique applications.

Equipment List




Propane tank, hose, torch & regulator; Sandpaper (40-60 grade) or wire brush; Knife, roller, rags & ethanol (min. 94%) cleanser; Temperature measuring device, Marking pencil; Standard safety equipment; gloves, goggles, hard hat, etc.

Backfilling Trench



Ensure there is adequate work space area around the pipe in the backfilling trench.

Flame Intensity




Adjust the flame according to outside conditions.

- Use moderate intensity (blue) flame for low wind, higher temps
- Use high intensity (blue) flame for high wind, lower temps


Always aim the torch perpendicular to the Casing Shrink Film and the CSC-X and move in a circumferential direction quickly around the jacket pipe. **Do not overheat the jacket pipe as it will burn with excessive heating.**

Casing Preparation




Check the CSC-X to ensure that it is not damaged. Before welding together the carrier pipes, slide the CSC-X as far away from the joint as possible.

General Drying and Cleaning




Use a propane torch with a moderate flame to dry the jacket pipe and carrier pipe. Use a dry, grease and lint-free rag to wipe clean the jacket pipe, carrier pipe and CSC-X.

Pipe Preparation




Remove any wet PUR foam from the end of the pre-insulated pipe.

Half-Shell Installation or Foaming



Using a triangular scraper, clean the edges of the jacket pipe to remove any burrs and dirt from the sealing area.

Half-Shell Installation or Foaming




Install the foam half-shells as per the manufacturing instructions. Alternatively, foam the joint using a removable mold.

CSC-X Position Marking




For convenience, centre the CSC-X over the joint and mark out two reference lines circumferentially on the jacket pipe (this will assist in preparation and positioning of the CSC-X). After marking the reference lines, slide the CSC-X away from the joint.

Surface Preparation




Clean the surface of the jacket pipe and the inside of the casing with a rag (150mm) to remove dirt. Degrease the surface of the jacket pipe and the inside of the CSC-X (150mm) using a grease and lint-free rag soaked in ethanol (min. 94%).

Surface Abrasion




Roughen the surface of the jacket pipe on both sides of the cutback and the inside of the CSC-X (150mm) using the sandpaper (40 to 60 grade).

Final Surface Cleaning



Using a dry, grease and lint-free rag, clean the roughened surface to remove any polyethylene or sand particles.

Pre-Heat




Using a moderate intensity (blue flame) torch, pre-heat 150mm (6") of the jacket pipe surface, on each side of the cutback, to 40°C (104°F); 125mm (5") towards the center of the joint from the marked lines and 25mm (1") outside of the marked lines. **Do not heat the foam half-shells or overheat the jacket pipe.**


WC-20R Film Installation



Partially remove the release liner and **gently** heat the underlap approximately 150mm (6") from the edge.



Beginning between the 10 and 2 o'clock positions, centre the film over the joint so that it will cover the PUR foam and overlap both ends of the jacket pipe. Remove the remaining release liner.




Tightly, wrap the film around the pipe, ensuring the overlap is sufficient. Visually inspect the wrapped film for the following:

- Film is in full contact with the foamed joint and jacket pipe.
- Film conforms to the foam profile.
- No cracks or holes in film backing.

In general, the WC-20R will shrink during the CSC-X application, however, the film can be heated to remove any wrinkling or to improve profile conformance (if required).


Adhesive Length (With Bulk Roll)



If not using the pre-cut adhesive from a kit, measure the circumference of the jacket pipe and cut two sealing strips long enough to allow for overlap.


The Length (L) should be the circumference + 50mm overlap

Pre-Warming (Inside of Casing)




Pre-warm the inside of the casing on each end (150mm). Use moderate intensity (blue) flame to make sure that the casing does not start to recover.

Pre-Warming




Pre-warm the pipe to 40°C-50°C (104°F-122°F) with moderate to high intensity (blue) flame. **Ensure the correct temperature with a temperature measuring device.** Do not exceed 60°C (140°C) as this makes the removal of release liner difficult.

Release Liner




Remove the thinner release liner (opposite the mesh side) from both adhesive strips and...

Adhesive Application



...apply the adhesive strips tightly around the jacket pipe with the mesh side facing up. The strips should be applied so that they are placed approximately 5mm inside of the marks. Make sure the adhesive is not stretched during wrapping. Partially peel-back the release liner on the underlap and wrap the strips around the jacket pipe so that they overlap.




Fold the release liner outwards to allow for easy removal after positioning the casing.

CSC-X Placement




Carefully slide the CSC-X over the joint, so that the edges are centered over the edge of the adhesive strips.


CSC-X Installation




Completely remove the release liners from the adhesive strips.




For CSC-X sizes 355mm and greater, it is recommended to use two installers working on opposite sides of the pipe. Using broad strokes and a medium flame, begin shrinking in the center of the CSC-X.



Shrink the center of the CSC-X evenly all around the pipe circumference. Keep the torches moving to avoid overheating any spots; ensure sufficient heat is applied at the bottom.




Use broad circumferential strokes and continue shrinking by moving horizontally towards one side.




Then continue towards the opposite end of the CSC-X.

Quality Check (Finger Probe Test)



With a gloved finger, press down on the shrunk area to ensure the backing and adhesive are soft. Also, use a gloved hand to check parts of the shrunk area between the 5 and 7 o'clock positions. If there are cool spots, the CSC-X should be reworked with additional heat.



Shrinking of the CSC-X has been completed when the casing system (film + CSC-X) has fully conformed to the pre-insulated pipe joint. Adhesive may ooze from the ends of the CSC-X.

Quality Check (Finger Tip Test)



As a final check, ensure that the entire CSC-X conforms intimately with the entire pipe surface. This can be checked by feeling the edges all around the circumference of the casing. If there is edge lifting, the edge should be reworked with additional heat.

Tension Tape Application



For casing sizes PE355 and above, wrap the supplied tension tape around both edges immediately after shrinking, while the casing is still soft (if the casing has cooled down; reheat it). **This ensures even cooling and conformance of the edges.**


CSC-X Completed Installation



Ensure that the entire casing system conforms to the jacket pipe and the circumference of the half-shells. Visually inspect the completed casing system for the following:

- CSC-X is in full contact with the pre-insulated pipe joint
- Adhesive may flow beyond both casing edges
- No cold spots, cracks or holes in casing backing.

Backfilling Guidelines



After shrinking is complete, the CSC-X should be left for as much time as possible prior to backfilling (minimum 1 hour). This ensures that the adhesive has cooled enough and that sealing is achieved. To prevent damage to the CSC-X, use selected backfill material (no sharp stones or large particles).

Storage & Safety Guidelines

To ensure maximum performance, store Canusa products in a dry, ventilated area. Keep products sealed in original cartons and avoid exposure to direct sunlight, rain, snow, dust or other adverse environmental elements. Avoid prolonged storage at temperatures above 35°C (95°F) or below -20°C (-4°F). Product installation should be done in accordance with local health and safety regulations.

These installation instructions are intended as a guide for standard products. Consult your Canusa representative for specific projects or unique applications at info@canuscps.com.

Western Hemisphere

SFL Canusa - WH
4757 93rd Ave NW
Edmonton, Alberta T6B 2T6
Canada

Tel: +1 587-754-8701

Europe

SealForLife Industries
Nijverheidsstraat 13
B-2260 Westerlo
Belgium

Middle East

SFL Canusa Middle East PPTS LLC
KLP5, Block B, Unit B-01,
Sector no.: KHIA8, Al Ma'mourah
PO Box 2621, Abu Dhabi,
The United Arab Emirates

Quality Management system registered to ISO 9001

Canusa warrants that the product conforms to its chemical and physical description and is appropriate for the use stated on the installation guide when used in compliance with Canusa's written instructions. Since many installation factors are beyond our control, the user shall determine the suitability of the products for the intended use and assume all risks and liabilities in connection therewith. Canusa's liability is stated in the standard terms and conditions of sale. Canusa makes no other warranty either expressed or implied. All information contained in this installation guide is to be used as a guide and is subject to change without notice. This installation guide supersedes all previous installation guides on this product. E&OE

Part No. 99060-215
IG_CSC-X_rev015